



---

# 2002 Bombardier Global Express

Serial No. 9089 | N65WL



## AIRCRAFT HIGHLIGHTS

- Engines on Rolls Royce Corporate Care
- APU on MSP Gold
- Batch 3.4 Avionics Upgrade
- FANS I/A – CPDLC
- Head-up Display (HUD)
- STARLINK Internet
- MTOW Increase to 98,000
- 240 Month Inspection Completed in 2022

### Airframe

Total Hours	6,812
Total Landings	2,547

### Engines

	Engine 1	Engine 2
Make	Rolls-Royce BR700-710A2-20	
Serial No.	12290	12291
Total Time	6,663	6,812
Total Cycles	2,492	2,547

### APU

Honeywell RE220 (GX)	
Serial No.	P-157
Total Time	5,115

### Programs

Engines	Rolls-Royce Corporate Care
APU	Honeywell MSP Gold
Maintenance Tracking	CAMP



[CLICK TO VIEW 3D CABIN TOUR](#)

## Avionics

- Honeywell Primus 2000 XP Avionics Suite
- Triple Honeywell IC-810 Integrated Avionics Computes with Six (6) 8" X 7" DU-870 Color IFIS Displays
- Triple Honeywell Laseref IV Long Range Navigations Systems
- Triple Honeywell AZ-840 Mico Air Data Computer
- Triple Honeywell CDU 820's
- Dual Honeywell RCZ-833M Transceivers and 3rd RCZ-833 VHF Transceiver
- Artex 406 MHz Emergency Locator Transmitter (ELT)
- Honeywell DFDR Digital Flight Data Recorder
- Honeywell HFR5-V Cockpit Voice Recorder (CVR) with DLR (120 Minutes)
- Tiple Honeywell Flight Management Systems (FMS)
- Dual Honeywell Global Positioning Systems (GPS)
- Dual Collins High Frequency Radios (HF-903 IA) with SELCAL
- Honeywell LSZ-860 Lightning Sensor System
- Dual Honeywell RNZ-85 I Integrated VHF Navigation Radios
- Dual Rockwell Collins ALT-4000 Radio Altimeters
- Honeywell Mark V EGPWS Terrain Awareness and Warning System
- Dual Honeywell RCZ-833M Transponders with Enhanced Mode S

## Additional Equipment

- STARLINK Internet
- Batch 3.4 Avionics Upgrade
- WAAS/LPV
- TCAS 7.1
- MTOW Increase to 98,000
- Head-up Display (HUD)

## Interior

- Passengers: Fourteen (14)
- Galley Location: Forward
- Forward Cabin: Two (2) Place Club Seats Opposite Single (1) Business Center Seat
- Mid Cabin: Four (4) Place Conference Group Opposite Two (2) Club Seats
- Aft Cabin: Three (3) Place Divan Opposite Two (2) Club Seats
- Crew Rest: Yes
- Last Refurbishment: March 2015

## Exterior

- White with Blue & Grey Stripes
- Last Refurbishment: 2015

## Maintenance

Inspection	Last Performed	Due
120 Month Inspection	July 2022	July 2032
240 Month Inspection	July 2022	July 2042





Kevin White | +1 850 501 8121 | [sales@element-aviation.com](mailto:sales@element-aviation.com) | [www.element-aviation.com](http://www.element-aviation.com)









951 Yamato Road Ste 275  
Boca Raton, FL 33431

CONTACT KEVIN WHITE FOR MORE INFORMATION

+1 850 501 8121

[sales@element-aviation.com](mailto:sales@element-aviation.com)

[www.element-aviation.com](http://www.element-aviation.com)